


GRABO

DISPLAY STAND INSTRUCTION MANUAL





GRABO DISPLAY STAND CONTENTS






NO	NAME	Number
1	Top_Display frame	1
2	mound layer	2
3	90° _Flat tube	2
4	Pull ring	2
5	Textured tiles	1
6	Wood	1
7	Material placement frame	2
8	Grabo Side_R	1
9	Grabo Side_L	1
10	U-bend flat pipe_R	1
11	U-bend flat pipe_L	1


NO	NAME	Number
12	front panel	1
A	M6x12 cross pan screw	12
B	M6x25 cross pan screw	8
C	M6x40 cross pan screw	8
D	M6x55 cross pan screw	4
E	M6 hex nut	12
F	M6 hex nut with cap	14
G	M6_flat_washer	12
H	Wire_rope	2
I	Wire_lockset	4




















Note*
**As a safety
precaution,
included is an
optional metal arm
(cross pan) to
secure the testing
materials down to
the display unit
table top, to
prevent the
materials being
dropped or
possible injury.**







Note*
Included is a tether cable to ensure the Grabo Tool cannot be separated from the display unit.

Wire cable can also be inserted through one of the four lifting Lugs.



GRABO®

**For any questions, comments, or concerns,
please reach out to us at:**

**info@grabo.com
www.GRABO.com**

**USA Headquarters
Grabo
6000 S. Eastern Ave.
Suite 8B
Las Vegas, NV. 89119**